

Evaluation Bull Dozer		<a href="http://www.mevas.eu">www.mevas.eu</a>			
Customer:		version 01/16			
Date:	08-01-2018				
Machine / type:	CAT D6T			location:	Hardenberg
Serial No.:	LKJ00541			Hour reading:	10842
Inspector:	Adam			Year:	2011
CE <input checked="" type="checkbox"/> EPA <input type="checkbox"/> A/C <input checked="" type="checkbox"/>		ripper <input type="checkbox"/>	LGP <input checked="" type="checkbox"/>		
laser control <input type="checkbox"/>	ripper valve <input checked="" type="checkbox"/>	Op-Manual <input checked="" type="checkbox"/>	Parts book <input type="checkbox"/>		
<b>cab</b>		cab doors	Good		
seat	Good	windows	Good		
switches	Good	wipers	Good		
gauges	Good	floor mats	Dirty		
aircon / heat	Not working	structure	Good		
<b>engine</b>		Serial No.	THX28179		
leaks & seals	No leaks	cooling system	Good		
oil condition & level	Good	blow by	Normal		
exhaust, muffler	Good	belts & filters	Good		
smoke	Normal	coolant condition	Good		
<b>exterior visual insp.</b>		sheets and doors	Good		
push frame	Good	tanks	Good		
engine hood	Good	lights	Good		
steps, hand rails	Good	paintwork	Repainted partially		
<b>hydraulics</b>		tilt cylinder			
hoses & lines	Good	angle cylinder	Rusty dots		
lift cylinders	LHS Rusty dots and leaks	ripper cylinder	N/A		
<b>functional test / play localization</b>					
pins push frame	Moderate play	pump noises	noisy when steering		
pins blade	Moderate play	electrics	Good		
pins ripper	-	transmission	Good		
equalizer bar	Ample play	brakes / clutches	Good		
stall test	1915-1620	steering	good		
<b>blade</b>	SU <input checked="" type="radio"/> SO <input type="radio"/> UO <input type="radio"/> PAT <input type="radio"/>				
front condition	welded	base (ground edge)	Good		
edge condition	worn	spill rack			
<b>U/C</b>	<b>Right side % good</b>	<b>Left % good</b>	track shoe width in mm:		
bushings	90%	90%	910		
shoes	90%	90%	rotating bushings <input type="checkbox"/>		
idler front	50%	50%			
idler rear	90%	90%	CAT System One <input checked="" type="checkbox"/>		
carrier roller	40%	90%	part No. track links:		
links	90%	90%	234-9699		
sprockets	50%	50%	part No. rollers		
rollers	30%-60%	60%-70%			
canon condition	OK, 8 cm extended	Ok, 7 cm extended			
<b>problems, details</b>	<del>Engine starts with engaged gear. → FIXED!</del> <i>S</i>				
	The machine is in general good condition. Some smaller repairs recommended.				
dimensions for transport L x W x H in meter:	7,6 (6,6 w/o blade) x 3,95 (3,2 w/o blade) x 3,35				